





Second floor in final clean. Duct entry point covering installed and complete.