## QFS, LLC

## dba: Quality Fire & Safety

P.O. Box 3071 McAlester, OK 74502 Oklahoma License # 296

## Name / Address

Oklahoma County Detention Center 201 N. Shartel Oklahoma City, OK 73102

			P.O. No.		Project	Wa	ork Order #
	Desc	ription			Qty	Rate	Total
SEMI ANNUAL INSPECTION: Semi-Annual Kitchen Suppression System Inspection 360 Degree Fusible Link, Needs replaced every six months. 16 Gram Actuator Cartridge and O-ring, Must be replaced every 12 months					2 11 2 1	90.00 10.50 25.75 75.00	180.00 115.50 51.50 75.00
Trip & Service Charge SEMI ANNUAL INSPECTION: Semi-Annual Kitchen Suppression System Inspection 360 Degree Fusible Link Trip & Service Charge					2 11 1	90.00 10.50 75.00	180.00 115.50 75.00
**Other parts that caps. ** only inv	: might be needed oiced if any are re		ngs and nozzle m	etal	1	75.00	75.00
				Su	ubtotal		\$867.50
Phone #	Fax #	E-mail		Sa	ales Tax (8	3.63%)	\$0.00
918-423-1117	918-423-9115	office@qfsok.c	com	Т	<b>Total</b> \$867.50		

## **ESTIMATE**

**Estimate Number** 3469

Estimate Date 6/6/2022

Ship To

Semi Annual Hood Inspection